

Shower Pan Must Be Set in Mortar Base for Proper Installation







HYDRO SYSTEMS, INC.

29132 Avenue Paine, Valencia, CA 91355 661.775.0686, fax 661.775.0668, www.hydrosystem.com Note: The information contained on this drawing is the sole property of Hydro Systems, Inc. Any reproduction in part or as a whole without the written permission of Hydro Systems, Inc. is prohibited.

| Title: | HP 6032 | | |
|--------|--------------|-------|---|
| Date: | May 10, 2019 | Rev: | _ |
| Scale: | None | Date: | |
| | | | |

Material: Acrylic or Gelcoat and Fiberglass, 1/4" nominal thickness